




Гайка для приваривания M16 или M20



|          | A      | B      | C | D  |
|----------|--------|--------|---|----|
| 1127-M16 | Ø 25,5 | Ø 20,8 | 5 | 20 |
| 1127-M20 | Ø 29,5 | Ø 24,8 | 5 | 20 |

## ТЕХНИЧЕСКИЕ ХАРАКТЕРИСТИКИ